

0500Z 20 DEC 63

~~TOP SECRET~~

TO DIRECTOR

FROM

25X1

ACTION OPS 1-12

INFO

PRIORITY

TOR: 0703Z 20 DEC 63

25X1

IN 55418

TO PRIORITY

25X1

104

A. G3256

25X1

25X1

B. B CAMERA/10,968/

C. 1. 9L PROCESSED ON TRENTON NBR 2, TEMPERATURE -  
PRIMARY 70.5, SECONDARY 80 DEGREES. DEVELOPMENT AS  
FOLLOWS: 0000 - 3403 FULL - 3403 - 3830 INTERMEDIATE;  
3830 - 3957 FULL - 3957 - 4742 INTERMEDIATE; 4742 - 5056  
FULL - 5056 - 5496 INTERMEDIATE.

2. 9R PROCESSED ON TRENTON NBR 1. TEMPERATURE -  
PRIMARY 70, SECONDARY 80 DEGREES. DEVELOPMENT SAME AS  
9L.

D. GAMMA 9L HEAD 2.64, TAIL 2.69.

9R HEAD 2.44, TAIL 2.62.

E. 9L, 8402/227-11-4-3

9R, 8402/223-12-15-4-3

F. QUALITY EVALUATION:

1. RECEIVED DRY IN METAL BOXES.

2. ADEQUATE

~~TOP SECRET~~

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

25X1

☐ 7758 (IN 55418)

~~TOP SECRET~~

PAGE TWO

3. CONTRAST IN PERCENT HIGH 5, MEDIUM 25, LOW 70

4. RESOLUTION - GOOD.

5. FOCUS - GOOD.

6. METERING - SLIGHTLY ERRATIC.

7. DATA RECORDING - CLEAR.

8. A DROP OFF IN QUALITY OCCURS TOWARD ALL OUTBOARD CORNERS OF THE FORMAT, WHICH IS NORMAL FOR CONFIGURATION S/N 113. PRESSURE ROLLER STATIC (CHATTER) IS PRESENT ALONG BOTH EDGES OF THE 9L FILM, AND ALONG THE INBOARD EDGE OF THE 9R FILM THROUGHOUT. THE VERTICAL INDICATOR DOT APPEARS OVER-EXPOSED AND BLOSSOMED. WEAK IMAGES OF THE ADJACENT POSITION INDICATOR LAMPS OCCUR WHEN THE CORRECT POSITION INDICATOR IS EXPOSED. METERING IS SLIGHTLY ERRATIC THROUGHOUT, BUT NO FORMAT OVERLAP OCCURS. THERE ARE 3504 TITLED FRAMES ON EACH SIDE. CLOUD COVER APPROXIMATE 25X15 PERCENT.

11. HELD AT ☐ FOR REPRODUCTION PURPOSES.

END OF MESSAGE

~~TOP SECRET~~